

**Work Order ID 70177**

Monday, May 30, 2011 2:40:24 PM



Page 1

Item ID: D3391-021

Accept



Setup Start



Revision ID:

Item Name: Fwd Tube Assembly

Stop



Start Date: 5/31/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 6/10/2011 Req'd Qty: 1.00



Customer:

Reference:

Approvals: Process Plan: MKDate: 11-05-20

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D3391	Rev H

100 0.00



Skidtubes

Skidtubes

Memo

0.00

Cut extrusion to 46.52 +0.010 -0.020

1 BB 11/06/09

110 0.00



BENDING MACHINE - SKIDTUBES

CNC Bend 1

CNC Delta 100 Bender

Memo

0.00

Bend as per Dwg D3391 Using Bend Prog 3391021

DP 11-6-2

120 0.00



QC5- Inspect part completeness to step on W/O

QC

Quality Control

Memo

0.00

1 Q 8B 11/06/09

W/O:

**WORK ORDER CHANGES**

<b>DATE</b>	<b>STEP</b>	<b>PROCEDURE CHANGE</b>	<b>By</b>	<b>Date</b>	<b>Qty</b>	<b>Approval</b> Chief Eng / Prod Mgr	<b>Approval</b> QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

<b>NCR:</b>		<b>WORK ORDER NON-CONFORMANCE (NCR)</b>						
<b>DATE</b>	<b>STEP</b>	<b>Description of NC</b> Section A	<b>Corrective Action</b> Section B			<b>Verification</b> Section C	<b>Approval</b> Chief Eng	<b>Approval</b> QC Inspector
			<b>Initial</b> Chief Eng	<b>Action Description</b> Chief Eng	<b>Sign &amp; Date</b>			

**NOTE:** Date & initial all entries

**Work Order ID 70177**

Monday, May 30, 2011 2:40:24 PM



Page 2

Item ID: D3391-021

Accept



Setup Start



Revision ID:

Item Name: Fwd Tube Assembly

Stop



Start Date: 5/31/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 6/10/2011 Req'd Qty: 1.00



Customer:

Reference:

Approvals:

Process Plan: \_\_\_\_\_ Date: \_\_\_\_\_ Tooling: \_\_\_\_\_ Date: \_\_\_\_\_

Run Start



QC: \_\_\_\_\_ Date: \_\_\_\_\_ SPC (Y/N): \_\_\_\_\_ Date: \_\_\_\_\_

Stop

Sequence ID/  
Work Center IDOperation  
DescriptionSet Up/  
Run Hours

Tool ID

Tool #

Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

130



HAAS CNC VERTICAL MACHINING #1

0.00

HAAS 1



Memo

0.00

HAAS CNC vertical machine #1

1-Machine as per Folio FA590 Rev. A & Dwg D3391 Rev. H  
Identify as D3391-1  
2-Deburr

11/06/08

1 0

140



QC2- Inspect parts off machine FAI/FAIB

0.00

QC



Memo

0.00

Quality Control

11/06/08

1 0

150



CONVENTIONAL MILLING MACHINE

0.00

Mill Conv

Conventional Milling Machine

Memo

0.00

Drill X1 Aft cap as per Dwg D3391 .1875" dia

AS 11/06/10

1 0

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_  
 Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

**Work Order ID 70177**

Monday, May 30, 2011 2:40:24 PM



Page 3

Item ID: D3391-021

Accept



Setup

Start



Revision ID:

Item Name: Fwd Tube Assembly

Stop



Start Date: 5/31/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 6/10/2011 Req'd Qty: 1.00



Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run

Start



QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/  
Work Center IDOperation  
DescriptionSet Up/  
Run Hours

Tool ID

Tool #

Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

160

QC2- Inspect parts off machine FAI/FAIB

0.00

0.00



QC

Memo

170

QC8- Inspect parts - second check

0.00

0.00



QC

Memo

Quality Control

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

**Work Order ID 70177**

Monday, May 30, 2011 2:40:24 PM



Page 4

Item ID: D3391-021

Accept



Setup Start



Revision ID:

Item Name: Fwd Tube Assembly

Stop



Start Date: 5/31/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 6/10/2011 Req'd Qty: 1.00



Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run

Start



QC:

Date:

SPC (Y/N):

Date:

Stop


**Sequence ID/  
Work Center ID**

180


**Operation  
Description**
**Set Up/  
Run Hours**

Tool ID

Tool #


**Plan  
Code**
**Accept  
Qty**
**Reject  
Qty**
**Reject  
Number**
**Insp.  
Stamp**

Skidtubes



0.00

Skidtubes


**Memo**

0.00

1-Drill float bag holes as per Dwg D3391 using DT8798(Do not open tow cap holes to finish size)  
(ONLY DRILL HOLES MARKED "A")

2-Drill Remaining two holes for tow cap using DT 8819 Locating off of .1875"  
holes drilled in previous step

3-Open tow cap holes to .208" as per Dwg D3391

4-Open Tow Ring hole to .640" as per Dwg D3391

5- open float bag holes 0.328" and counter sink as per dwg D3391

6-Deburr & Scribe Batch number Inside aft end.

7-Transfer drill D3391-021 with D3391-023


190



QC5- Inspect part completeness to step on W/O

0.00

QC


**Memo**

0.00

DP 11-6-13

Quality Control

DP 11-6-14

SD 11-6-14

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_  
 Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

**Work Order ID 70177**

Monday, May 30, 2011 2:40:24 PM

Page 5



Item ID: D3391-021

Accept



Setup Start



Revision ID:

Item Name: Fwd Tube Assembly

Stop



Start Date: 5/31/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 6/10/2011 Req'd Qty: 1.00



Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/  
Work Center IDOperation  
DescriptionSet Up/  
Run Hours

Tool ID

Tool #

Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

200



Chemical Conversion Coat per QSI005 4.1

0.00

*1 d 26 11/06/15*

HandFinish

Memo

0.00

Hand Finishing

210



QC3- Inspect Part Finish

0.00

*DP 11-6-15*

QC

Memo

0.00

Quality Control

220



Skidtubes

0.00

Skidtubes

Memo

0.00

Skidtubes

1-instal spacers as per dwg D3391  
 A/R Magnabond 6398 batch: *11/06/15*  
 exp. date: *11/06/15*  
 cure time 12hrs. as per QSI015  
 2-grind crossbolt flush  
 3-back drill crossbolt if necessary

*3 06 11/06/15*  
*3 06 11/06/15*

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

**Work Order ID 70177**

Monday, May 30, 2011 2:40:24 PM



Page 6

Item ID: D3391-021

Accept



Setup Start



Revision ID:

Item Name: Fwd Tube Assembly

Stop



Start Date: 5/31/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 6/10/2011 Req'd Qty: 1.00



Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/  
Work Center IDOperation  
DescriptionSet Up/  
Run Hours

Tool ID

Tool #

Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

230

QC5- Inspect part completeness to step on W/O

0.00

Sun 06/10/20



QC

Quality Control

235

Pressure Wash per QSI005 4.3

0.00



HandFinish

Memo

0.00

14 M 11/06/20

Hand Finishing

AND REALODINE AS PER PAR09-043

M 116 964

240

White Gloss(Ref:4.3.5.1) per QSI005 4.3-Alum

0.00



Powdercoat

Memo

0.00

Powder Coating

START TIME: 2:35 OVEN TEMPERATURE: 400°  
FINISH TIME: 3:05

1 BL 11-6-20-

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_  
 Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

**Work Order ID 70177**

Monday, May 30, 2011 2:40:24 PM



Page 7

Item ID: D3391-021

Accept



Setup Start



Revision ID:

Item Name: Fwd Tube Assembly

Stop



Start Date: 5/31/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 6/10/2011 Req'd Qty: 1.00



Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run

Start



QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/  
Work Center IDOperation  
DescriptionSet Up/  
Run Hours

Tool ID

Tool #

Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

250

QC3- Inspect Part Finish

0.00



QC

Quality Control

1 φ M 1106121

255

Skidtubes

0.00



Skidtubes

Memo

0.00

1 φ M 1106121

Skidtubes

\*\*\*\* install D3591-1 spacer as per DSI9364 and wearplate and gasket as per  
DWG \*\*\*\*

257

QC5- Inspect part completeness to step on W/O

0.00



Quality Control

Memo

0.00

S W o 4 121

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_  
 Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

**Work Order ID 70177**

Monday, May 30, 2011 2:40:24 PM



Page 8

Item ID: D3391-021

Accept



Setup Start



Revision ID:

Item Name: Fwd Tube Assembly

Stop



Start Date: 5/31/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 6/10/2011 Req'd Qty: 1.00



Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/  
Work Center IDOperation  
Description

260

Identify as per dwg & Stock Location: W10

Packaging

Packaging

Set Up/  
Run Hours

Tool ID

Tool #

Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp


0.00

D412-742-043/B70177

1

6

M



280



QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

MF

11-06-2022

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_  
 Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

## Picklist Print

Monday, May 30, 2011 2:40:18 PM

Page 1

**Work Order ID:** 70177



A standard linear barcode is positioned horizontally across the page, consisting of vertical black bars of varying widths on a white background.

**Parent Item:** D3391-021

**Parent Item Name:** Fwd Tube Assembly

**Start Date:** 5/31/2011

**Required Date:** 6/10/2011

Start Qty: 1.00

Required Qty: 1.00

**Comments:** IPP A 05.09.13 New issue KJ/JLM  
IPP B 06.02.10 Dwg rev.D ecn 773 EC  
IPP C 06.05.02 Added inspections EC  
IPP D 07.03.13 rev F dwg EC  
IPP E 07.11.07 revG dwg ecn1053P EC verified by: DD  
IPP Rev:f ECN 1056 07-11-12 DD verified by: EC  
IPP Rev:G 08-09-08 new process (ecn 08-510) DD verified by:EC  
IPP Rev:H 08-09-10 revH as per dwg DD verified by:EC  
IPP Rev J 09.02.02 added hardware EC verified by: DD

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

# Picklist Print

Page 2

Monday, May 30, 2011 2:40:18 PM

Work Order ID: 70177



Parent Item: D3391-021



Parent Item Name: Fwd Tube Assembly

Start Date: 5/31/2011

Required Date: 6/10/2011

Start Qty: 1.00

Required Qty: 1.00

D3564-13



Manufactured

No

255

Each

30.0000

1

1

  
SL u106121

Wearshoe

	<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
FP016	18		
69280	18		
FP017	12		
<u>66805</u>	12		X1

D3566-13



Manufactured

No

255

Each

44.0000

1

1

  
SL u106121

Gasket

	<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
FP	26		
69281	26		
FP014	18		
<u>68341</u>	18		X1

AN960C10L

NAS1149C0332

R

Purchased

No

255

Each

0.0000

10

10

M117881



(x10) SL u106121

washer

AN3C4A



Purchased

No

255

Each

2,337.000

10

10

  
SL u106121

BOLT

	<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
ST350	2337		
<u>117094</u>	955		X10
117313	82		
117688	800		
117795	500		

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_  
 Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

# Picklist Print

Monday, May 30, 2011 2:40:19 PM

Page 3

Work Order ID: 70177



Parent Item: D3391-021



Parent Item Name: Fwd Tube Assembly

Start Date: 5/31/2011

Required Date: 6/10/2011

Start Qty: 1.00

Required Qty: 1.00

D3672-1



Manufactured

No

255

Each

1,204.000

4

4



M117717

Phenolic Washer

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
ST074	1204	
64177	704	X4
66821	500	

AELS-1032-130



Purchased

No

255

Each

0.0000

2

2

M117717



(X2) M117717

INSERT

AELS-1032-225



Purchased

No

255

Each

0.0000

10

10

M117717



(X10) M117717

INSERT

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_  
 Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	70177
Description: Float Skidtube (412)	Part Number:	D3391-1
Inspection Dwg: D3391 Rev: H		Page 1 of 1


## **FIRST ARTICLE INSPECTION CHECKLIST**

## X First Article      Prototype

Measured by:	<u>AMR/SB</u>	Audited by:	<u>JL</u>	Prototype Approval:	N/A
Date:	11/06/08,	Date:	11/06/13	Date:	N/A

Rev	Date	Change	Revised by	Approved
A	06.04.27	New Issue P/O D3391-011/-021	KJ/JLM	
B	06.06.19	Tolerances revised per D3391 Rev. E	KJ/JLM	
C	07.03.21	Dimensions removed per Dwg rev. F	KJ/JLM	
D	07.11.23	Dwg Rev. updated	KJ/EC/DD	
E	09.12.14	Dwg Rev updated	KJ	

8 7 6 5 4 3 2 1



W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_


Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

8 7 6 5 4 3 2 1

D D C C B B A A

**D3391-043 FLOAT SKIDTUBE ASSEMBLY PARTS LIST**

QTY	PART NUMBER	DESCRIPTION
X	D3391-043	FLOAT SKIDTUBE ASSEMBLY
1	D3391-021	FWD TUBE ASSEMBLY
1	D3391-023	MID TUBE ASSEMBLY
1	D3391-025	AFT TUBE ASSEMBLY
1	D3564-1	WEARSHOE
1	D3564-3	WEARSHOE
2	D3564-5	WEARSHOE
2	D3566-1	GASKET
2	D3566-5	GASKET
2	D3591-1	BUSHING
24	AN3C4A	BOLT
12	AN3C6A	BOLT
12	AN3C7A	BOLT
44	AN960C10L	WASHER

**GENERAL NOTES**

- FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1 POWDER COAT WHITE (4.3.5.1) PER DART QSI 005 4.3
- SPRAY INSIDE OF TUBE WITH A COAT OF LPS LABORATORIES "LPS-3" AFTER FINISH AND AFTER INSTALLATION OF INSERTS. COAT ALL EXPOSED FASTENERS WITH LPS LABORATORIES "LPS PROCYON" AFTER FINAL ASSEMBLY. CLEAN EXCESS OFF POWDER COATING WITH MEK DEGREASER.
- TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- UNITS: INCHES UNLESS OTHERWISE NOTED
- USE DART DRILL TEMPLATE DT8217 TO LOCATE AND DRILL Ø0.297 SIZE HOLES FOR WEARSHOE INSERTS. CBORE AS NOTED AND INSTALL INSERTS EXCEPT WHERE INDICATED.

**DEO ATTACHED****RELEASED**  
08-09-05 M

DESIGN	PH	<b>DART AEROSPACE USA, INC</b>
DRAWN	AJS	PORT HADLOCK, WA
CHECKED		DRAWING NO.
MFG. APPR.		D3391
APPROVED		REV. H
DE APPR.		SHEET 2 OF 8
DATE	08.08.20	TITLE
		412 FLOAT SKIDTUBE
		NTS

COPYRIGHT © 2005 BY DART AEROSPACE USA, INC  
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL. AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS  
NOT TO BE USED FOR ANY OTHER PURPOSE OR DISCLOSED TO ANY PERSON WITHOUT  
WRITTEN PERMISSION FROM DART AEROSPACE USA, INC

8 7 6 5 4 3 2 1

A

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector


Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_  
 Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


NOTE: Date & initial all entries

8 7 6 5 4 3 2 1


D




**D3391-1 CUTTING DETAIL**  
(MAKE FROM D6013-047 SKIDTUBE MATERIAL)




**D3391-011-021 BENDING DETAIL**  
(MAKE FROM D3391-1)




**SECTION A-A**  
SCALE 2X



**SECTION B-B**  
SCALE 2X



**SECTION C-C**  
SCALE 2X



**VIEW Z-Z**  
SCALE 2X

DEO ATTACHED

RELEASED  
08.08.20

DESIGN	P.H.	DART AEROSPACE USA, INC
DRAWN	AUS	PORT HADLOCK, WA
CHECKED		DRAWING NO.
MFG. APPR.		REV. H
APPROVED		D3391
DE APPR.		SHEET 3 OF 8
DATE	08.08.20	TITLE
		412 FLOAT SKIDTUBE
		NTS

COPYRIGHT © 2005 BY DART AEROSPACE USA, INC.  
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS  
NOT TO BE USED FOR ANY OTHER PURPOSE THAN THAT FOR WHICH IT WAS PROVIDED.  
REPRODUCTION IN WHOLE OR IN PART IS PROHIBITED WITHOUT  
WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.


8 7 6 5 4 3 2 1

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_  
 Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



**DETACHED**

**RELEASED**  
*08-09-05 M*

DESIGN	PH	DART AEROSPACE USA, INC
DRAWN	AJS	PORT HADLOCK, WA
CHECKED		DRAWING NO.
		D3391
MFG. APPR.		REV. H
APPROVED	AM	SHEET 4 OF 8
DE APPR.		TITLE
		412 FLOAT SKIDTUBE
DATE	08.08.20	SCALE
		NTS


COPYRIGHT © 2005 BY DART AEROSPACE USA, INC  
THIS DOCUMENT CONTAINS CONFIDENTIAL INFORMATION. IT IS  
NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT  
WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_  
 Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries




Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_  
 Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries




W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_  
 Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries




W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_  
 Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

8/20/77



D3391-015 BENDING AND DRILLING DETAIL  
(SEE CBORE DETAIL BELOW)

INSTALL D3670-4200 SPACER  
SEAL WITH MAGNOBOND 6398

GRIND FLUSH  
PRIOR TO PAINTING

14 PL

D3391-015 ASSEMBLY AND CBORE DETAIL  
(SEE TABLE)


INSTALL D3670-4200 SPACER  
SEAL WITH MAGNOBOND 6398

GRIND FLUSH  
PRIOR TO PAINTING


4 PL

D3391-015/025 AFT TUBE ASSEMBLY PARTS LIST

QTY - 015	QTY - 025	PART NUMBER	DESCRIPTION
X	D3391-015	AFT TUBE ASSEMBLY	
X	D3391-025	AFT TUBE ASSEMBLY	
1	1	D6014-090	AFT TUBE
1	1	D2646	AFT CAP
1	1	D3537-1	WEARPAD
1	1	D3537-7	WEARPAD
1	1	D3553-1	GASKET
1	1	D3553-3	GASKET
14	4	D3670-4200	SPACER
2	2	D3672-1	WASHER
14	14	AELS-1032-130	INSERT
12	12	AELS-1032-225	INSERT
4	4	ALS4-428-165	INSERT
6	6	AN3C4A	BOLT
4	4	AN3C5A	BOLT
10	10	AN960C10L	WASHER




SECTION U-U  
SCALE 3X




SECTION CC-CC  
SCALE 3X

D3391-025 ASSEMBLY AND CBORE DETAIL  
(SEE TABLE)



DETAIL T  
SCALE 4X



DETAIL T  
SCALE 4X

DEO ATTACHED

RELEASED  
08-09-05 M

CBORE HOLES MARKED CB1-CB4 AS FOLLOWS AND  
INSTALL AELS-1032-XXX AFTER FINISH AS NOTED

HOLES MARKED	QTY D3391-015	QTY D3391-025	CBORE	P/N
CB1	12	12	Ø0.430 X 0.170	AELS-1032-225
CB2	4	4	Ø0.430 X 0.170	AELS-1032-130
CB3	6	6	Ø0.430 X 0.040	AELS-1032-130
CB4	4	4	NONE	AELS-1032-130

DESIGN	PH	DART AEROSPACE USA, INC
DRAWN	AJS	PORT HADLOCK, WA
CHECKED		
MFG. APPR.		DRAWING NO. D3391
APPROVED		REV. H
DE APPR.		SHEET 8 OF 8
DATE	08.08.20	TITLE
		SCALE NTS
		COPYRIGHT © 2005 BY DART AEROSPACE USA, INC
		THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR OTHER PURPOSES OR COPIED OR REPRODUCED IN WHOLE OR IN PART BY ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

A.

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_  
 Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

DRAWING NO. D3391	TITLE 412 FLOAT SKIDTUBE	REV. H	<b>DART AEROSPACE USA, INC</b> <b>ENGINEERING ORDER</b>	D.E.O. NO. D3391-H-1	SHEET NO. SHEET 1 OF 1	SCALE NTS
DRAWN <i>CP</i>	CHECKED <i>LM</i>	MFG. APPR. <i>MM</i>	APPROVED <i>MD</i>	DE APPR. <i>MM</i>		
DATE 09.09.23	DATE 09.09.24	DATE 09/09/25	DATE 09/09/30	DATE 09/09/30	DATE 09/09/30	

**PURPOSE:**

LPS-3 IS NO LONGER USED DURING ASSEMBLY OF D3391-041/-043 SKIDTUBES.

**CHANGE:**

AMEND NOTE 2 OF D3391-041/-043 SKIDTUBE ASSEMBLIES (ZN A6-1, A6-2) AS FOLLOWS:

- 2) ~~SPRAY INSIDE OF TUBE WITH A COAT OF LPS LABORATORIES "LPS-3" AFTER FINISH  
AND AFTER INSTALLATION OF INSERTS.~~ COAT ALL EXPOSED FASTENERS WITH  
LPS LABORATORIES "LPS PROCYON" AFTER FINAL ASSEMBLY, CLEAN EXCESS  
OFF POWDER COATING WITH MEK DEGREASER.

**RELEASED**  
2010 -02 - 02

*#70177*

*MP*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_  
 Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries